


Universal Wall Mount Bracket

[UNI-SWB-002] instructions


colebrook **bossonsaunder**s




WARNING

Before you start check to see the wall is strong enough to support the load

1 Remove spacers from bracket




2 Mount bracket to wall




! Bolts should be Xmm in diameter and suitable for 12kg (26.5lbs) min

3 Attach Universal wall bracket to mount




4 Tighten adjuster screw




! Do not overtighten Recommended 5 N/m


5 Add spacers to arm




6 Add arm to the bracket and insert spacer screw



7 Tighten spacer screw




Maximum Loading



MAX 12kg/26.5lb

! Do NOT exceed maximum recommended load

8 Repositioning bracket



WARNING

- Ensure the wall is suitable to take the weight of the screen and mounting
- Do not use this product for any purpose other than that for which it was designed
- Hold the screen tightly when making adjustments
- Care should be taken to avoid trapping fingers
- Do not dismantle or modify the screen mounting
- Supported weight must not exceed 12Kg (26.5lb)

MAINTENANCE AND INSPECTION

- Ensure all screws are tightened and occasionally adjust if needed.
- Clean with a damp cloth, NO solvents.

DISCLAIMERS

- The use of power tools, lever bars or excessive force during the installation, or re-configuration of the product will invalidate your guarantee.
- Failure to observe the recommendations in the use, and configuration of these products may affect your guarantee.

International patents pending

UNI-SWB-002-INST-A JULY2012

www.colebrook**bossonsaunder**s.com

